

PRODUCT NAME: SKIT WINDSHIELD WASHER CONCENTRATE
PRODUCT CODE: 50346

SECTION V- REACTIVITY DATA (continued)

HAZARDOUS DECOMPOSITION OR BYPRODUCTS: In fire will decompose to CO, CO₂, various hydrocarbons.
HAZARDOUS POLYMERIZATION: Will not occur.

SECTION VI- HEALTH HAZARD DATA

INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE: Excessive inhalation of vapors can cause nasal and respiratory irritation, central nervous system effects including dizziness, weakness, fatigue, headache and possible unconsciousness and even death.

NATURE OF HAZARD:

SKIN: Can cause slight irritation.

EYES: Causes irritation, possible corneal injury.

CARCINOGENICITY: NTP? IARC? OSHA REGULATED?

Presently not on any list.

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE: N/A.

EMERGENCY AND FIRST AID PROCEDURES:

DIGESTION: If swallowed, immediately drink two glasses of water and induce vomiting by either giving IPECAC syrup or by mouth to a conscious person. Get medical attention immediately.

INHALATION: Remove patient to fresh air. Get medical attention immediately.

SKIN AND EYE CONTACT:

EYES: Immediately flush eyes with large amounts of water for at least 15 minutes. Hold eyelids apart to ensure complete flushing. Do not attempt to neutralize with chemical agents. Get medical help immediately.

SKIN: Remove contaminated clothing and flush skin with water. Wash with soap and water until material has been removed. Seek medical attention immediately.

SECTION VII- PRECAUTIONS FOR SAFE HANDLING AND USE

STEPS TO BE TAKEN IN CASE LARGE AMOUNT OF MATERIAL IS RELEASED OR SPILLED: Remove all sources of ignition, avoid breathing vapors and remove with inert absorbent. Dispose of as hazardous waste.

WASTE DISPOSAL METHOD: Dispose of in accordance with federal, state, and local regulations regarding pollution.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Keep away from heat, sparks, or open flame.

OTHER PRECAUTIONS: NA.

SECTION VIII- CONTROL MEASURES

RESPIRATORY PROTECTION: Usually not required if it is used as it is described on the label.

VENTILATION: Provide adequate ventilation to keep mist or vapors below allowable exposure levels.

PROTECTIVE GLOVES: For prolonged or repeated contact, wear gloves which are recommended by glove supplier for protection against materials in Section II.

EYE PROTECTION: Recommend safety glasses with unperforated sideshields.

OTHER PROTECTIVE CLOTHING OR EQUIPMENT: Long sleeves and long pants.

WORK/hygienic practices: Do not smoke while using. Wash hands after use.

SECTION IX- DISCLAIMER

NOTE: THE INFORMATION IN THIS DOCUMENT IS BELIEVED TO BE CORRECT AS OF THE DATE ISSUED. HOWEVER, NO WARRANTY OF MERCHANTABILITY, FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY OTHER WARRANTY IS EXPRESSED OR TO BE IMPLIED REGARDING THE ACCURACY OR COMPLETENESS OF THIS INFORMATION OR THE PRODUCT, THE SAFETY OF THIS PRODUCT, OR THE HAZARDS RELATED TO ITS USE. THIS INFORMATION AND PRODUCT ARE FURNISHED "AS IS" AND ON THE CONDITION THAT THE PERSON RECEIVING THEM SHALL MAKE THEIR OWN DETERMINATION AS TO THE SUITABILITY OF THE PRODUCT FOR THEIR PARTICULAR PURPOSE AND ON THE CONDITION THEY ASSUME THE RISK OF THEIR USE THEREOF.

